1426-1446 East Baltimore Street (Commercial Buildings)
1430 East Baltimore Street
Baltimore (Independent City)
Maryland

HABS No. MD-904-B

HABS MD, 4-BALT, 153 B-

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

ym (0-920 une 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS MD. 4-BALT.

23 Sept. 1985

ARCHITECTURAL DATA FORM

6 :	COUNTY	COUNTY		TOWN OR VICINITY	
No ex line d					
Mary I and HISTORIC NAME OF STRUCTURE	UNCLUOF SOURCE FOR	LUDE SOURCE FOR NAME)		Baltimore HABS NO.	
A. Arraya a same and a					
1426-46 East Baltimore Street (Commercial Buildings) SECONDARY OR COMMON NAMES OF STRUCTURE				MD-904-B	
1430 East Baltimore		•			
1430 East Baltimore	Street				
COMPLETE ADDRESS (OESCRIBE	LOCATION FOR RURAL	SIT ES)			
1430 E. Baltimore Stre	et ·		٠		
DATE OF CONSTRUCTION (INCLUOE SOURCE)		ARCHITECT(S) (INCLUOE SOURCE)			
C. 1860 (1869 Sachsey map)		unknown			
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)					
Original use presumed	to be shop with re	sidence above.	Double entrance	e and	
storefront typical of	this building type	. Late 19th C.	Commercial bui	lding which	
contributes to streets	cape.				
STYLE (IF APPROPRIATE) Italianato	·				
MATERIAL OF CONSTRUCTION (//		SYSTEMSI			
Brick bearing walls; we		•	of wood doom		
SE AND DIMENSIONS DE STRE		JUN PLANS UN SEPAI	raie pages are a		
Overall 13' x 66' From	nt 13' x 31' Rear	12' x 35'			
EXTERIOR FEATURES OF NOTE			-		
Metal cornice, red brid	ck (painted) commor	ı bond, segmenta	l-arched window	v openings.	
	•				
INTERIOR FEATURES OF NOTE (C	ESCRIBE FLOOR PLANS	, IF NOT SKETCHEO)			
Undeterminable	•				
MAJOR ALTERATIONS AND ADDI	TIONS WITH DATES			······	
	-				
c 1911 Lot combined w/ 1426 E. Baltimore Street. Alterations at that time assumed to be the construction of the present structure. Storefront alterations.					
be the construction of	the present strave	uie. Storellon	t afterations.		
PRESENT CONDITION AND USE		<u> </u>			
Currently vacant, this	building is suffer	ing from extens	ive water damag	je. It is unsafe	
to enter and inspect. OTHER INFORMATION AS APPRO		ears stable.			
For photographs, see	HABS No. MD-904.				
Building is to be demo		ront room and re	ebuilt to a new	design for	
cooperative apartments					
SOURCES OF INFORMATION (INC.	LUDING LISTING ON NA	TIONAL REGISTER, S	TATE REGISTERS, I	ETC.)	
B69 Sachsey Map, 1887	Bromley Map, Sa-bo	rn Maps 1902, 19	911, 1927, 1932		
COMPILER, AFFILIATION			DAT		

Peter C. Doo, AIA Walter Schamu & Associates.